



F1

F2


*Cut red lines, score outside of box, but do not fold down until neck is stuck in place.


F5


bottom last


F3


F4


















M4




L1




M5



Seal front at very end
of brush/plinf/pole assembly



L3



L2